

Annexure D

BUILDING SAFETY CERTIFICATE

No. 2913

Dated: ...19/5/2026

It is certified that the existing building Doon Public School at Shivpuri Link Road, Gwalior M.P. is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	2 1

The building is owned/occupied by Doon Public School have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of MPPWD Division, Gwalior (M.P.) on...18/05/2026..(date of inspection) in the presence of Principal Ms. Neha Iqbal, Shivpuri Link Road, Gwalior M.P. and that the building/premises is fit for occupancy for running school with effect for the year 2026-27 for a period of one year in accordance with rule and subject to compliance of the specific conditions as appended.

Alkatre
SIE

C.S.
Asst. Eng.
Executive Engineer
P.W.D. Dn.No.1, Gwalior

Asst. Eng.
Assistant Engineer
P.W.D. Road Sub Division
Gwalior (M.P.)

कार्यालय कार्यपालन यंत्री, लोक निर्माण विभाग, संभाग क्रं.-1 ग्वालियर

☎0751-2371231, Email: eepwdlgwl@nic.in

क्रमांक 2913 / तक. / भवन सुरक्षा प्रमाण-पत्र / 2026-27

ग्वालियर दिनांक : 19/5/26

प्रति,

✓ सयुक्त संचालक
लोक शिक्षण
संभाग ग्वालियर

विषय :- भवन सुरक्षा प्रमाण-पत्र सी.बी.एस.ई. बोर्ड के प्रारूप अनुसार जारी करने के सम्बंध में।

सन्दर्भ :- आपका कार्या. पत्र क्रं./मान्यता/भ.सु.प्र.प./2026/1858 दिनांक 15.05.2026

विषयान्तर्गत सन्दर्भित पत्र के तारतम्य में लेख है कि अशासकीय दून पब्लिक स्कूल, शिवपुरी लिंक रोड ग्वालियर के भवन का अनुविभागीय अधिकारी लोक निर्माण विभाग पथ उपसंभाग ग्वालियर एवं सम्बंधित उपयंत्री द्वारा निरीक्षण कराया गया उनके द्वारा प्रस्तुत स्कूल का भवन सुरक्षा प्रमाण-पत्र आपकी ओर आवश्यक कार्यवाही हेतु संलग्न प्रेषित है।

सहपत्र :- भवन सुरक्षा प्रमाण-पत्र।


(देवेन्द्र सिंह भदौरिया)
कार्यपालन यंत्री
लोक निर्माण विभाग संभाग क्रं.-1
ग्वालियर